

Conversion Factors

Concentration	
1,000,000 ppm	100%
100,000 ppm	10%
10,000 ppm	1%
1000 ppm	0.1%
100 ppm	0.01%
10 ppm	0.001%
1 ppm	0.0001%
1000 ppb	1 ppm
100 ppb	0.1 ppm
10 ppb	0.01 ppm
1 ppb	0.001 ppm
1000 ppt	0.001 ppm
100 ppt	0.0001 ppm
10 ppt	0.00001 ppm
1 ppt	0.000001 ppm
1000 ppt	1 ppb
100 ppt	0.1 ppb
10 ppt	0.01 ppb
1 ppt	0.001 ppb