

Conversion Factors

Dew Point – Moisture	
Dew Point °F	Moisture ppm (vol/vol)
-130	0.1
-120	0.25
-110	0.63
-105	1.00
-104	1.08
-103	1.18
-102	1.29
-101	1.40
-100	1.53
-99	1.66
-98	1.81
-97	1.96
-96	2.15
-95	2.35
-94	2.54
-93	2.76
-92	3.00
-91	3.28
-90	3.53
-89	3.84
-88	4.15
-87	4.50
-86	4.78
-85	5.3
-84	5.7
-83	6.2
-82	6.6
-81	7.2
-80	7.8
-79	8.4
-78	9.1
-77	9.8
-76	10.5
-75	11.4
-74	12.3
-73	13.3
-72	14.3
-71	15.4
-70	16.6
-69	17.9
-68	19.2
-67	20.6
-66	22.1
-65	23.6
-64	25.6
-63	27.5
-62	29.4
-61	31.7
-60	34.0